DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000794 Address: 333 Burma Road **Date Inspected:** 05-Nov-2007

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** Plate Material MTR's

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector Timothy McClendon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

Plate Material Storage Yard (check samples):

Quality Assurance (QA) Inspector McClendon received plate material list for Caltrans check test samples, plate list No.22~31 (second batch) received from American Bridge/Fluor (ABF). QA Inspector McClendon went to the ZPMC plate material storage yard accompanied by ZPMC Quality Control Shen Xue jun. QA Inspector McClendon verified, plate ID #, Grade, Batch # and material test reports. QA Inspector McClendon wrote lot numbers and marked the direction of rolling on each of the 10 samples. Caltrans lot numbers for check samples are as follows.

No. 22, ID#070206Q226, Grade A709M-345F2-X, Batch No. A702428, MTR No. A44152, Remarks-SPCM, Lot No. B94-006-07.

No.23, ID#070416Q040, Grade A709M-345F2-X, Batch No. A706684-2, MTR No. 1265, Remarks-OBG, Lot No. B94-007-07.

No. 24, ID#070416Q161, Grade A709M-345F2-X, Batch No. A709325, MTR No. 1888, Remarks-OBG, Lot No. B94-008-07.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

No. 25, ID#NG070514G159, Grade A709M-345F2-X, Batch No. 071015530202, MTR No. 3344, Remarks-SPCM, Lot No. B94-009-07.

No. 26, ID#NG070515G078, Grade A709M-345F2-X, Batch No. 072016586101, MTR No. 3335, Remarks-OBG, Lot No. B94-010-07.

No. 27, ID#070306Q124, Grade A709M-345F2-X, Batch No. A704045, MTR No. 381, Remarks-OBG, Lot No. B94-011-07.

No. 28, ID#070206Q231, Grade A709M-345F2-X, Batch No. A702264, MTR No. A44153, Remarks-OBG. Lot No. B94-012-07.

No. 29, ID#070416Q163, Grade A709M-345F2-X, Batch No. A703316, MTR No. 3089, Remarks-OBG. Lot No. B94-013-07.

No. 30, ID#070416Q172, Grade A709M-345F2-X-S, Batch No. A709352, MTR No. 1772, Remarks-OBG. Lot No. B94-014-07.

No. 31, ID#070506Q181, Grade A709M-345F2-X-S, Batch No. A710855-2-1, MTR No. 1721, Remarks-OBG. Lot No. B94-015-07.

The above lot numbers were written on the each check sample along with an arrow showing the direction of rolling.

The lot numbers, date, batch/heat numbers, plate type/grade and plate thickness were all entered on the Caltrans check sampling tracking log for Caltrans Project 04-0120F4. Mr. Shen informed QA Inspector McClendon that the check samples will be sent to Shanghai Testing Lab tomorrow.

Summary of Conversations:

No relevant conversations spoken on this day.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	McClendon, Timothy	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer